



Photo 1 – View of the wreckage where it came to rest. (Photo courtesy of Textron)



Photo 2 – View of the wreckage from the tail looking forward. (Photo courtesy of Textron)



Photo 3 – View of the engine separated from the airframe. (Photo courtesy of Textron)



Photo 4 – View of the metallic debris in the oil filter. (Photo courtesy of Textron)



Photo 5 – View of the airplane's radar track.