



Photo 1: View of the initial impact point ground scar and main wreckage



Photo 2: Forward view of the main wreckage



Photo 3: View of the right wing and fuselage



Photo 4: View of the throttle lever and elevator trim indicator