



Photo 1 – View of the left side of the wreckage.



Photo 2 – View of the right side of the wreckage.



Photo 3 – View of the cockpit instrument panel. (Photo courtesy of Lycoming)



Photo 4 – View of the front of the engine, removed and suspended for examination.



Photo 5 - View of the back of the engine, removed and suspended for examination.



Photo 6 – View of the disassembled wood propeller. (Photo courtesy of Lycoming)