



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Wreckage Photo Array

ERA19LA004



Photo 1 – Runway Scars (Photo Courtesy of FAA)



Photo 2 – Airplane – View from Right Rear (Photo Courtesy of FAA)



Photo 3 – Airplane – View from Left Rear (Photo Courtesy of FAA)



Photo 4 – Airplane – View from Left (Photo Courtesy of FAA)



Photo 5 – Airplane – View from Right (Photo Courtesy of FAA)



Photo 6 – Airplane – View from Front (Photo Courtesy of FAA)



Photo 7 – Rear Fuselage Damage (Photo Courtesy of FAA)



Photo 8 – Ground Scarring and Airplane (Photo Courtesy of FAA)



Photo 9 – Propeller 1 (Photo Courtesy of FAA)



Photo 10 – Propeller 2 (Photo Courtesy of FAA)



Photo 11 - Propeller 3 (Photo Courtesy of FAA)