



Photo 1 – Right side view of the airplane where it came to rest along a road. (Photo courtesy of the FAA)



Photo 2 – View of the damaged main landing gear. (Photo courtesy of the pilot)



Photo 3 – View of the partially disassembled carburetor. (Photo courtesy of the pilot)