



Photo 1 – View of front of airplane showing damage to right wing. (Courtesy of FAA)



Photo 2 – View of broken right wing and spar. (Courtesy of FAA)



Photo 3 – Photo of recovered aviation fuel from airplane; about 5 gallons. (Courtesy of FAA)