



Photo 1 – Airplane at the Accident Site (Photo Courtesy of FAA)



Photo 2 - Empennage of Airplane Lodged in Trees (Photo Courtesy of FAA)



Photo 3 – Spare Fuse Blown as Found by FAA Inspector (Photo Courtesy of FAA)



Photo 4 – View of Engine Separated from the Firewall (Photo Courtesy of FAA)