

Date: 11/01/2018 Hours: TTAF:5555.1 Hobbs:1916.4

Tail#: N111TA

Make: Piper

Model: PA28-180

S/N: 28-3746

Annual inspection performed. All panels were opened IAW Piper MM. All chains, pulleys, cables, and hinges were lubed. Wheel bearings were inspected and repacked.

Left inboard brake pad was replaced. 'ELT tested. Battery due 12-2019. Overhauled engine mount was installed due to prop ground strike with all new hardware. Battery was top charged. Serviceable nose gear was installed. New bearings, upper and lower, were installed in nose gear. Serviceable nose wheel was built up using new 6.00x6 tire and tube. New bearings and races were installed on nose wheel. All tire pressures were set per the POH. Nose strut was service with NO2. Nose wheel steering and rudder were rerigged IAW MM. All AD's complied with through AD ToolBox this date. I find this aircraft airworthy at this tie and returned to service.

Name: Dan Giallourakis

Co: DGW Aircraft Service LLC

Cert

Sign:

AGENCY & CERTIFICATE NO.
WORK PERFORMED/RETURNED TO SERVICE