



Photo 1 – Main Wreckage (FAA Photo)



Photo 2 – Right Wing Damage (FAA Photo)



Photo 3 - Right Wing Damage (FAA Photo)



Photo 4 – Engine (NTSB Photo)



Photo 5 – Spark Plugs (NTSB Photo)