



Photo 1 –FAA Digital Photograph. Right Rear Quartering View Depicting The Accident Site.



Photo 2 - FAA Digital Photograph. Rear View Depicting The Accident Site.



Photo 3 - FAA Digital Photograph. View Depicting The Damage to the Left Lower Wing Skin and Aileron of Accident Airplane.



Photo 4 - FAA Digital Photograph. Frontal View Depicting The Front of the Accident Airplane and the Impacted Left Wing of the Parked Airplane.



Photo 5 - FAA Digital Photograph. View Depicting The Right Wheel Assembly and Leaking Fluid Beneath the Right Brake.



Photo 6 - FAA Digital Photograph. Close-Up View of the Lower Portion of the Right Main Landing Gear Tire Depicting Leaking Fluid from the Right Brake.