



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19LA069




Photo 1 – View of Airplane from Left Side (Photo Courtesy of FAA)



Photo 2 – View of Airplane Tail (Photo Courtesy of FAA)



Photo 3 – No. 1 Rocker Cover, Broken Valve Spring Seat, Damaged Valve Key (Photo Courtesy of FAA)




Photo 4 – View of No. 1 Cylinder after Rocker Cover Removed (Photo Courtesy of FAA)



Photo 5 – View of No. 1 Intake Valve Head (Photo Courtesy of FAA)



Photo 6 – No. 1 Piston Head

