



Photo 1 –View of Airplane at rest (Courtesy of FAA)



Photo 2 – View of Snarge on Nose Wheel (Courtesy of FAA)



Photo 3 – Aft view of airplane (Courtesy of FAA)



Photo 4 – View of underside of engine (Courtesy of FAA)



Photo 5 – View of Underside of Engine Cowling with Snarge