



Photo 1 – View of front of airplane showing left wing damage




Photo 2 – View of right side of airplane showing right wing damage



Photo 3 – View of left side of airplane showing vertical stabilizer damage