



Photo 1 – Front view of the wreckage. (Photo courtesy of the FAA)



Photo 2 – View of the landing lights, the gouges in the ground and runway in the background. (Photo courtesy of the FAA)



Photo 3 – Right side view of the wreckage. (Photo courtesy of the FAA)