



Photo 1 – Main Landing gear collapse, left-wing view. (FAA)



Photo 2 – Left Gear, (FAA)



Photo 3 – Right gear, (FAA)




Photo 4 – Part number of actuator (Mechanic)



Photo 5 – Pinion Bearing separated from actuator (Mechanic)