



Photo 1 – View of the wing leading edge and fuselage amongst the trees where it came to rest. (Photo courtesy of the FAA)




Photo 2 – View of the top of the wing and engine. (Photo courtesy of the FAA)



Photo 3 – View of the cockpit where it came to rest, nearly vertical against a tree. (Photo courtesy of the FAA)