

Photo Array for ERA19LA136

Photographs provided by the Federal Aviation Administration



Photograph 1 - Accident airplane as seen from the front left side.



Photograph 2 - Accident airplane as seen from the right side.

Photo Array for ERA19LA136

Photographs provided by the Federal Aviation Administration



Photograph 3 - Accident airplane as seen from the left side.



Photograph 4 - Accident airplanes instrument panel.

Photo Array for ERA19LA136

Photographs provided by the Federal Aviation Administration



Photograph 5 - Accident airplanes fuel selector valve.