



Photo 1 – FAA Digital Photograph. View Taken from Initial Touchdown in Field Looking Towards Contacted Pole. The Airplane Had Been Moved in this Photograph.



Photo 2 – FAA Digital Photograph. View of the Power Pole Contacted By the Left Wing.



Photo 3 - FAA Digital Photograph. Forward View of the Airplane. Note the Damage to the Outer Portion of the Left Wing Due to Contact with the Power Pole.



Photo 4 - FAA Digital Photograph. View taken Aft of the Left Wing Looking Forward Depicting the Inboard Portion of the Wing. Note the Compression Buckle on the Upper Wing Skin and Displacement of the Wing.



Photo 5 - FAA Digital Photograph. View Depicting the Damage to the Outer Leading Edge of the Left Wing.