



Photo 1 – View of runway environment



Photo 2 – Satellite image of direction of flight (blue line (supplied by the pilot))



Photo 3 – View of tree that main rotor blades impacted



Photo 4 – Forward view of helicopter cabin section showing post-crash fire damage



Photo 5 -View of fuselage of helicopter showing post-crash fire damage



Photo 6 – View of tail boom and tail rotor showing buckling and post-crash fire damage