



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19LA149



Photo 1 – Airplane, view from left (Photo courtesy of Connecticut State Police)



Photo 2 – Airplane, view from rear (Photo courtesy of Connecticut State Police)



Photo 3 – Airplane, view from right (Photo courtesy of Connecticut State Police)



Photo 4 – Airplane, view from front (Photo courtesy of Connecticut State Police)



Photo 5 – Left wing damage (Photo courtesy of FAA)



Photo 6 – Propeller (Photo courtesy of FAA)



Photo 7 – Propeller damage (Photo courtesy of FAA)



Photo 8 – Damage to power lines (Photo courtesy of FAA)