



**Photo 1 – Main Wreckage (National Park Service Photo)**




**Photo 2 - Engine (National Park Service Photo)**




**Photo 3 – Aft Fuselage (National Park Service Photo)**



**Photo 4 – Left Wing and Cabin (National Park Service Photo)**



**Photo 5 – Left Wing Root Damage (National Park Service Photo)**



**Photo 6 – Right Wing (National Park Service Photo)**




**Photo 7 – Right Wing (National Park Service Photo)**



**Photo 8 – Landing Gear Floats (National Park Service Photo)**



**Photo 9 – Landing Gear Floats (National Park Service Photo)**



**Photo 10 – Damage to Floats (National Park Service Photo)**



**Photo 11 – Exemplar Landing Gear Attachment Hardware (Salvage Company Photo)**