



Photo 1 – Overhead view of the airplane where it came to rest. (Photo courtesy of the FAA)



Photo 2 – View of the damage to the right wing leading edge. (Photo courtesy of the FAA)



Photo 3 – View of the right wing partially separated from the fuselage. (Photo courtesy of the FAA)