



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation


ERA19LA219

August 25, 2020



Photograph 1¹ – Accident airplane – left side view.

¹ Photograph provided by the Federal Aviation Administration.



Photograph 2² – Accident airplanes fuel selector valve position.

² Photograph provided by the Federal Aviation Administration.