



Photo 1 – View of Hi Max airplane destroyed in field (FAA Photo)



Photo 2 – View inside the fuselage, showing structural damage (FAA Photo)