



**Photo 1 – Digital Photograph From Pilot. Right Side View of the Airplane At the Accident Site. Note the damage to the Vertical Stabilizer and Rudder.**