



Photo 1 –View of Airplane at rest (Courtesy of FAA)




Photo 2 – View of Engine after Accident



Photo 3 – View of control arm separated from propeller governor.