



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA19LA239



Photo 1 – View of Airplane from Left Side (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Rear (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Right Side (Photo Courtesy of FAA)



Photo 4 – View of Airplane from Front (Photo Courtesy of FAA)



Photo 5 – Close-up View of Right Horizontal Stabilizer (Photo Courtesy of FAA)



Photo 6 – Close-up View of Left Horizontal Stabilizer (Photo Courtesy of FAA)



Photo 7 – Close-up View of Fuselage Damage (Photo Courtesy of FAA)