



**Photo 1 – View of helicopter wreckage on the side of building**



**Photo 2 – View of helicopter wreckage rear view**



**Photo 3 – View of wreckage forward view**



**Photo 4 – View of corrosion within the right magneto**