



Weather Observations

NSE Airport 20 Miles NNE of Accident Site

Aaron McCarter
Air Safety Investigator
Eastern Region Aviation

August 13, 2019

METAR/SPECI from **KNSE, Milton, Whiting Field North (United States).**

SA 13/08/2019 19:56->	METAR KNSE 131956Z 04004KT 10SM TS SCT035CB SCT090 BKN150 BKN250 28/26 A2990 RMK AO2 SLP108 OCNL LTGICCG VC NE TS NE MOV LTL VCSH NE T1 SET T02780261 \$=
SA 13/08/2019 18:56->	METAR KNSE 131856Z 33004KT 10SM TS SCT033CB BKN070 BKN120 28/26 A2990 RMK AO2 RAE38 SLP109 OCNL LTGICCG VC NW-N TS NW-N MOV SW T1 SET P0006 T02780261 \$=
SP 13/08/2019 18:11->	<i>SPECI KNSE 131811Z VRB03KT 6SM -TSRA BR SCT030CB SCT060 BKN100 28/26 A2990 RMK AO2 OCNL LTGICCG OHD TS OHD MOV S T1 SET P0004 T02780256 \$=</i>
SA 13/08/2019 17:56->	METAR KNSE 131756Z 34005KT 5SM -TSRA BR SCT035CB BKN085 OVC250 28/26 A2991 RMK AO2 TSB26 SLP112 OCNL LTGICCG OHD TS OHD MOV SW T1 SET 6 / / / / T02780256 10328 20256 PNO \$=
SP 13/08/2019 17:38->	<i>SPECI KNSE 131738Z 00000KT 3SM -TSRA BR SCT030CB BKN055 OVC110 28/26 A2991 RMK AO2 TSB26 OCNL LTGICCG VC SW TS SW MOV SW T1 SET T02830261 PNO \$=</i>
SP 13/08/2019 17:27->	<i>SPECI KNSE 131727Z 08004KT 2SM +TSRA BR SCT030CB BKN055 OVC110 28/27 A2991 RMK AO2 TSB26 OCNL LTGICCG VC SW TS SW MOV SW T1 SET T02830272 PNO \$=</i>
SP 13/08/2019 17:11->	<i>SPECI KNSE 131711Z 00000KT 5SM -RA SCT025TCU BKN100 OVC250 30/26 A2991 RMK AO2 TCU OHD T1 SET T03000256 PNO \$=</i>
SP 13/08/2019 17:04->	<i>SPECI KNSE 131704Z VRB05KT 1/2SM +RA SCT025TCU BKN100 OVC250 30/25 A2992 RMK AO2 TCU OHD T1 SET T03000250 PNO \$=</i>
SA 13/08/2019 16:56->	METAR KNSE 131656Z VRB03KT 1 1/2SM RA SCT025 SCT100 BKN250 32/27 A2992 RMK AO2 RAB54 SLP117 T2 SET P0000 T03170267 \$=
SA 13/08/2019 15:56->	METAR KNSE 131556Z VRB05KT 10SM FEW025 FEW120 BKN250 32/27 A2993 RMK AO2 SLP118 T03220272 \$=