



Photo 1 – Airplane Wreckage and Wreckage Path (courtesy FAA)



Photo 2 – Airplane Wreckage Being Recovered (courtesy FAA)



Photo 3 – 24v Battery Negative (left) and Positive (right) Leads (photo NTSB)



Photo 4 – 24v Positive (left) and Negative (right) Battery Connectors (photo NTSB)



Photo 5 – Positive Battery Lead Connector (Photo NTSB)



Photo 6 - Negative Battery Lead Connector (Photo NTSB)