



Investigative Photographs

ERA19LA258

March 22, 2021

Peter Wentz
Air Safety Investigator
Eastern Region Aviation



Photograph 1¹ – Accident airplane – front view.

¹ Photograph provided by Aircraft Owner.



Photograph 2² – Accident airplane – right side view.



Photograph 3³ – Accident airplane – left side view.

² Photograph provided by Aircraft Owner.

³ Photograph provided by Aircraft Owner.



Photograph 4⁴ – Accident airplane – right wing damage.

⁴ Photograph provided by Aircraft Owner.