



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Engine Rear Accessory Section (Photo Courtesy of Lycoming)



Photo 3 – Engine Crankshaft Idler Gear And Flange (Photo Courtesy of Lycoming)



Photo 4 – Nuts, Bolts, And Safety Wire From Engine Crankshaft Idler Gear Flange (Photo Courtesy of Lycoming)