

A copy of the surveillance videos are located in the public docket.

NTSB Review of Surveillance Video

ERA19LA285

Video courtesy of the Bloomsburg Fair, Bloomsburg, Pennsylvania

GATE 5 PRE ENTRY AREA

377

The red circle denotes the position of the helicopter. This moment captures the time the helicopter entered the right yaw and stopped its forward momentum.

9/28/2019

7:33:42.242 PM

Figure1 – Surveillance camera view, showing the helicopter at the moment it entered the right yaw

PARKING LOT TOWER PTZ

26

This is a second camera view at the moment the helicopter entered the right yaw and stopped its forward momentum. Note, the red circle denotes the landing light of the helicopter.

9/28/2019

7:33:42.281 PM

Figure 2 – A second surveillance camera view, showing the helicopter at the moment it entered the right yaw

PARKING LOT TOWER PTZ

164

9 ft

This camera view shows the helicopter, seconds before its impact with the cars below the flight path. According to the Pilot's Operating Handbook, the length is 9 ft from the landing skids to the top of the main rotor mast

9/28/2019

7:33:51.473 PM

Figure 3 – View of the helicopter and its measured dimensions




Figure 4 – View of the helicopter and its estimated height above ground

PARKING LOT TOWER PTZ

This camera view shows the helicopter, at the moment it impacted the car below its flight path.



9/28/2019

7:33:52.407 PM

Figure 4 – View of the helicopter at the moment it impacted terrain and vehicles