



Photo 1 – View of left front quarter of airplane showing landing gear and engine cowl damage. (Courtesy of FAA)



Photo 2 – View of right side of plane showing fuselage buckling and landing gear damage. (Courtesy of FAA)



**Photo 3 – Right profile view of airplane showing overall damage to fuselage and engine compartment.
(Courtesy of FAA)**



Photo 4 – View of nose of airplane showing damage to propeller and ground scars. (Courtesy of FAA)