



Photo 1 – Courtesy of FAA- View of airplane at rest on embankment



Photo 2 - Courtesy of FAA- side view of airplane showing collapse nose gear and buckled engine cowling.



Photo 3 - Courtesy of FAA- showing buckled engine mount