



Photo 1 – View of the airplane next to the taxiway where it came to rest. (Photo courtesy of the FAA)



Photo 2 – View of the left side of the airplane. (Photo courtesy of the FAA)



Photo 3 – View of the left brake caliper. (Photo courtesy of the FAA)



Photo 4 – View of the damage to the left tire. (Photo courtesy of the FAA)