



Photo 1 – View of propeller strikes on runway



Photo 2 – View of fire damaged left side of airplane



Photo 3 – View of underside of left wing fire damaged and landing gear down and locked



Photo 4 – View of right side of airplane at rest on runway on the underside



Photo 5 – View of airplane being raised off the runway with landing gear up and locked