



Photo 1 –View of gap between right flap and fuselage (Courtesy of FAA)



Photo 2 – View of gap between left flap and fuselage (Courtesy of FAA)



Photo 3 – View of fuselage wrinkling (Courtesy of FAA)