




Photo 1 – View of the right side of the wreckage and damage to right wing. (Photo courtesy of the pilot)




Photo 2 – View of the belly of the airplane, broken main landing gear, and damage to left wing. (Photo courtesy of the pilot)