



Photo 1 – View of Airplane after Recovery (Cape Air)



Photo 2 – Close-up View of Damaged Structure (Cape Air)