



Photo 1 – View of left-wing damage (photo courtesy of the FAA).



Photo 2 - View of left-wing damage (photo courtesy of the FAA).



Photo 3 - View of engine mount damage (photo courtesy of the FAA).



Photo 4 - View of fire wall damage (photo courtesy of the FAA).