



Photo 1 – Propeller, Propeller Spinner, and Left Wing Tip Damage - Courtesy of Harford Air Services



Photo 2 – Lower Left Wing Damage - Courtesy of Harford Air Services)



Photo 3 – Top View of Upper Left Wing Damage – Courtesy of Harford Air Services



Photo 4 – Aft View of Upper Left Wing Damage – Courtesy of Harford Air Services