



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA20CA300

October 28, 2020



Photograph 1¹ – Accident airplane – right side view.

¹ Photograph provided by Federal Aviation Administration.



Photograph 2² – Accident airplane – left wing substantial damage.

² Photograph provided by Federal Aviation Administration..



Photograph 3³ – Accident airplane – left wing substantial damage.

³ Photograph provided by Federal Aviation Administration.



Photograph 4⁴ – Accident airplane – left wing substantial damage.

⁴ Photograph provided by Federal Aviation Administration.



Photograph 5⁵ – Left side tail section.

⁵ Photograph provided by Federal Aviation Administration.