



Photo 1 – Initial Impact Point (NTSB Photo)



Photo 2 – Main Wreckage (NTSB Photo)



Photo 3 - Main Wreckage (NTSB Photo)



Photo 4 - Main Wreckage (NTSB Photo)



Photo 5 – Cut Wood Found Along Debris Path (NTSB Photo)



Photo 6 – Gyro Housing (NTSB Photo)



Photo 7 – Gyro (NTSB Photo)



Photo 8 – Propeller Blade (NTSB Photo)



Photo 9 – Vacuum Pump (NTSB Photo)



Photo 10 – Vacuum Pump (NTSB Photo)