



Photo 1 – View of Airplane as Found (Piper)



Photo 2 – View of Cockpit and Cabin Area as Found (Piper)



Photo 3 – View of Engine Un-cowled (Piper)



Photo 4 – View of Fuel Selector Valve as Found (Piper)



Photo 5 - View of Fuel Selector Valve after Recovery (Piper)




Photo 6 – View of Fuel Selector Plate as Found (Piper)




Photo 7 – View of Fuel Selector Plate Witness Marks (Piper)