



Photo 1 – Front Right View of Airplane at Accident Site



Photo 2 – Rear View of Airplane at Accident Site



Photo 3 – Front Right View of Airplane and Canopy at Accident Site



Photo 4 – Cockpit Area



Photo 5 – Fuel Filter Screen



Photo 6 – Left Side View of Engine



Photo 7 – Right Side View of Engine



Photo 8 – Rear View of Engine



Photo 9 – Carburetor Bowl



Photo 10 –Water Finding Paste Tests Positive (paste turns pink) in Carburetor Bowl



Photo 11 – Rust Colored Fluid drained from Carburetor Bowl