



Photo 1 – View of the initial impact point, between two houses.



Photo 2 – View of the separated propeller and wreckage debris.



Photo 3 – View of the fuselage.



Photo 4 – View of debris along the wreckage path.



Photo 5 – View of the wreckage path from the initial impact point.



Photo 6 – View of the wreckage path from the engine looking back to the initial impact point.



Photo 7 – View of the separated engine.




Photo 8 – View of the airplane’s radar flight track.