



Photo 1 – Aft view of airplane showing fuselage damage.



Photo 2 – Right-side view of airplane showing right wing damage.



Photo 3 – Forward view of airplane showing crush damage.



Photo 4 – Left side view of airplane showing crush damage.