



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20FA118



Photo 1 – View of the main wreckage, from the engine to the empennage.



Photo 2 – View of the bottom and left side of the fuselage. (Photo courtesy of the FAA)



Photo 3 – View of the fuselage. (Photo courtesy of Piper)



Photo 4 – View of portions of the right wing. (Photo courtesy of Piper)



Photo 5 – View of portions of the left wing. (Photo courtesy of Piper)




Photo 6 – Google map view of the wreckage.