



Photo 1 – View of right front quarter of airplane at rest on the side of the runway. Note gear up configuration and propeller damage. (Courtesy of FAA)



Photo 2 – View of damage to underside of fuselage. (Courtesy of FAA)



Photo 3 – View of damage to fuselage and right landing gear door. (Courtesy of FAA)



Photo 4 – Airport surveillance video screen capture of airplane shortly after it came to rest. (Courtesy of Airport Authority)